

Technical Bulletin

This bulletin does NOT pertain to stations receiving programming via the Starguide or XDS Pro4 receivers. Please disregard.

Stations receiving programming via the Wegener Unity 4000, Satcuiser and Samsung receivers please carefully read the following.

Our satellite space segment provider Microspace will be making a change to the satellite signal parameters and this WILL affect your receiver.

This change will take place at 9:15 am eastern time on March 5th, 2010.

Wegener Unity 4000 receivers

Wegener Unity 4000 receivers should expect this change transparently however, in the event your receiver does not make the change to the new carrier settings a “Recovery Checklist” will be posted on the Microspace website at http://www.microspace.com/crc_update/crc_unity4000.shtml

Prior to the March 5th change over, Microspace will begin uploading new search tables to the Wegener Unity 4000 receivers that will contain the new carrier settings but will not be initiated until the March 5th date. These uploads are already underway and will continue once every hour until March 4th. This upload will be confirmed by an email notification on the front panel or the receiver. If you have additional Unity 4000 receivers as backups they should be brought online immediately so they can receive the uploads.

For assistance with any of the procedures, contact **Microspace Network Control** at **(919) 850-4503** or **The Information Radio Network** at **800-829-8111, ext 1358**.

Samsung Receivers:

All Samsung receivers will have to be updated manually. These receivers will not except the uploads.

Step by step instructions will be posted on the Microspace website at http://www.microspace.com/crc_update/crc_samsung.shtml

DO NOT make these changes to the receiver before the March 5th change over. If you make the changes prior to the March 5th change over you WILL lose your audio service.

For assistance with any of the procedures, contact **Microspace Network Control** at **(919) 850-4503** or **The Information Radio Network** at **800-829-8111, ext 1358**.

Satcruiser Receivers:

All SatCruiser receivers will have to be updated manually. These receivers will not except the uploads.

Step by step instructions will be posted on the Microspace website at http://www.microspace.com/crc_update/crc_SatCruiser.shtml

DO NOT make these changes to the receiver before the March 5th change over. If you make the changes prior to the March 5th change over you WILL lose your audio service.

For assistance with any of the procedures, contact **Microspace Network Control** at **(919) 850-4503** or **The Information Radio Network** at **800-829-8111, ext 1358**.